中文由机器翻译，以英文为准。 Chinese text is machine-translated, the English text applies.

包装与装车报告

Packing and loading report, MA-04

对象 Subject	3 件货物，为一台拆解的机器 3 packages containing a dismantled machine
委托方 Client	Muster Maschinenbau GmbH (虚构)
制造商 Manufacturer	Przykład Sp. z o.o. (虚构)
地点和日期 Place and date	波兹南，04.03.2026 Poznań, 04.03.2026
依据 Basis	装箱单、包装要求、验收未完成事项 Packing list, packing specification, open items from acceptance
在场人员 Present	制造商项目负责人和装配人员，Office-Remscheid Manufacturer's project lead and fitter, Office-Remscheid

结果一览 Result at a glance

9	1	2
合格 OK	提示 Note	已现场解决 Fixed on site

三件货物均已装车，车辆于 14:20 离开。出发前缺少一个标签和一个护角，均已现场补上。第 3 件的薄膜有破损。

All three packages were loaded, the truck left at 14:20. Before departure one label and one edge protector were missing, both were added on site. The film on package 3 is torn.

未完成事项 Open items

没有未完成事项。

No open items.

检查点位置 Location of inspection points



全部检查项 All items

编号	检查项和结果 Item and finding	结果 Result
文件 Documents		
A1	按装箱单清点件数 3 件全部到齐 3 of 3 packages present	**合格** OK
A2	运单已填写 CMR 运单已填写，副本见附件 CMR consignment note completed, copy attached	**合格** OK
A3	查看验收未完成事项 3 项均可见已完成 3 of 3 items visibly closed	**合格** OK
包装 Packing		
B1	木箱无可见损伤 未见损伤，已拍摄所有侧面 No damage visible, all sides photographed	**合格** OK
B2	每件都有标签 第 3 件没有标签 Package 3 has no label 制造商答复: 出发前已贴标签，见照片	**已现场解决** Fixed on site

编号	检查项和结果 Item and finding	结果 Result
B3	封箱前查看防锈措施 薄膜袋已封口，看到干燥剂 Film bag sealed, desiccant seen	**合格** OK
B4	倾斜指示器已安装且未触发 2 号箱上有倾斜指示器，未触发 Tilt indicator on crate 2, not triggered	**合格** OK
B5	薄膜完好 第 3 件的薄膜有破损 Film on package 3 is torn	**提示** Note
装车 Loading		
C1	记录车牌和封条号 两个车牌和封条号已拍照 Both registrations and seal number photographed	**合格** OK
C2	拍摄绑带和护角 1 号箱右侧绑带下缺少护角 Crate 1: edge protector missing under the right strap 制造商答复: 司机已补上护角，见照片	**已现场解决** Fixed on site
C3	在标记点起吊 1 号箱在标记点起吊 Crate 1 lifted at the marked points	**合格** OK
C4	出发 14:20，篷布已关闭并加封 14:20, curtain closed and sealed	**合格** OK

照片 Photos

示例中为示意图，实际报告中为照片。 The sample shows drawings, a real report shows photos.



B2 第 3 件没有标签
Package 3 has no label



B4 2 号箱上有倾斜指示器，未触发
Tilt indicator on crate 2, not triggered



B5 第 3 件的薄膜有破损
Film on package 3 is torn



C2 1 号箱右侧绑带下缺少护角
Crate 1: edge protector missing under the right strap



C3 1 号箱在标记点起吊
Crate 1 lifted at the marked points

本报告的性质 What this report is

本报告记录现场看到的情况以及制造商演示或测量的内容。它不是正式验收、安全检测或 CE 评估。是否放行由委托方决定。

This report records what could be seen at the visit and what the manufacturer demonstrated or measured. It is not a formal acceptance, not a safety inspection and not a CE assessment. The client decides on release.

中文由机器翻译，以英文为准。 Chinese text is machine-translated, the English text applies.

签字表示本人在场并确认自己的说明。 The signature confirms attendance and the signer's own statements.

制造商代表
For the manufacturer

编制人
Prepared by